



Denison

Denison Mines (USA) Corp.
1050 17th Street, Suite 950
Denver, CO 80265
USA

Tel : 303 628-7798
Fax : 303 389-4125

www.denisonmines.com

May 5, 2008

State of Utah, Department of Natural Resources
Department of Oil, Gas and Mining
1594 West North Temple, Suite 1210
P.O. Box 145801
Salt Lake City, Utah 84114-5801

Paul Baker:

Re: Response to Inspection Report dated April 16, 2008 for Pandora Mine M/037/012.

I received your inspection report dated April 16, 2008 on May 1, 2008 and wanted to respond and provide information on the status of our tamarisk removal at the Beaver Shaft. Denison removed and treated the tamarisk in April of this year. Although the tamarisk was cut down and treated, Denison is aware that ongoing maintenance will be required and will continue to keep you updated. Denison will also keep you updated on potential vent hole reclamation activities at the Pandora Mine site. Photographic documentation of the tamarisk removal is attached.

Please contact me (303) 389-4136 if you have any questions.

Respectfully.

Christy Woodward

Christy Woodward
Environmental Coordinator
Denison Mines Corp.

CC: Denison File
Terry Wetz, Denison Mines (USA) Corp.

RECEIVED
MAY 06 2008
DIV. OF OIL, GAS & MINING

Beaver Shaft Tamarisk Control

Pictures of the Tamarisk treatment this spring in the channel around the shaft.



